



Servo Position Potentiometer



Battery Voltage Measurement



MCU 5v Voltage Regulator

NOTE: J1 must be disconnected for serial programming MCU to prevent to voltage regulator.

OpenServo - www.openservo.com		
OpenServo v2		
Mike Thompson	Rev 2.1 Aprlil 1st, 2006	Page 1 of 2



MOSFET H-Bridge

OpenServo - www.openservo.com		
OpenServo v2		
Mike Thompson	Rev 2.1 April 1st, 2006	Page 2 of 2